


PACP Report with Pipe Run and Incident Snapshots

Surveyed by: DAN		Certificate number: U-716-07004752		Owner:		Customer:		Drainage area:		P/O number:		Sheet number:	
Pipe segment ref.: SMH050A_SMH050				Start date/time: 20220309 13:54		Street: GABLE LN				City: SMITHVILLE			
Location details:				Upstream MH No: SMH050A				Rim to invert:		Grade to invert:		Rim to grade:	
Pipe use: SS		Direction: D		Flow control:		Downstream MH No: SMH050				Rim to invert:		Grade to invert:	
Height: 8 in.		Width:		Shape: C		Material: PVC		Lining method:		Pipe joint length:		Total length: 40.400 ft.	
Length surveyed: 40.400 ft.		Purpose:		Sewer category:		Media label:		PreCleaning: L		Date cleaned:		Weather: 1	
Project name: Sewer Cleaning & CCTV - Project No. 210670				Additional info:									


Grade	Structural:					O&M:					Overall:	
	Amount of Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Amount of Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0	0000	0.0	0	0	0	0000	0.0	0	0.0
2	0	0				0	0					
3	0	0				0	0					
4	0	0				0	0					
5	0	0				0	0					

Observations

Distance	Video Ref.	PACP Code	Continuous	S/M/L	Value Inches (mm)		%	Joint	Circumferential Location		Rating	Image Ref.	Remarks
					1st	2nd			At/From	To			
0.0 ft.		AMH						<input type="checkbox"/>	/			SMH050A_SMH050_A MH_0.0 ft.JPG	SMH050A
0.0 ft.		MWL					5	<input type="checkbox"/>	/			SMH050A_SMH050_M WL_0.0 ft.JPG	
40.4 ft.	00:10:19	AMH						<input type="checkbox"/>	/			SMH050A_SMH050_A MH_40.4 ft.JPG	SMH050



Photos



At: 0 ft. AMH - Manhole
 Joint: No SMH050A



At: 0 ft. MWL - Miscellaneous Water Level
 Joint: No 5 %



At: 40.4 ft. AMH - Manhole
 Joint: No SMH050



At: 40.4 ft. AMH - Manhole
 Joint: No SMH050