

Project:		Date/Time:	June 28 2024 -
Street and City:	1350 Holland Rd. - Marion	Weather:	Unknown Weather
Owner:		P.O. #	
Customer:		Inspection Status:	Remote Inspection
Surveyor Name and Certificate:	Dan Shrodes U-716-07004752	Inspection Level:	2
Reviewer Name and Certificate:	chad pauls P0036127-022022	MH:	DC2





Asset Details and Measurements

MH Use:	Combined	Access Type:	AMH
Rim to Invert:	10.2	Pre-Cleaning:	No Pre-Cleaning
Rim to Grade:	0.4	Purpose:	Maintenance related
Grade to Invert:	9.8	Surface Type:	Gravel





MH Ratings

Overall Quick Rating: 211B			
Structural Quick Rating:	1A00	O&M Quick Rating:	2116
Overall MH Rating Index: 1.1			
Structural MH Rating Index:	1.0	O&M MH Rating Index:	1.1
Overall MH Rating: 20.0			
Structural MH Rating:	12.0	O&M MH Rating:	8.0


Observation Images

Photo	Distance	Description	Time
	0.6	SRI - component:CMI Continuous: S01 Clock from 12 to 12 Grade = 1	000003
	1	IWJ - component:CMI Joint: True Clock from 4 to 5 Grade = 2	000003
	1.9	SRI - component:CMI Continuous: F01 Clock from 12 to 12 Grade = 1	000004
	2	SRI - component:COI Continuous: S02 Clock from 12 to 12 Grade = 1	000004

Observation Images

	Photo	Distance	Description	Time
		4.3	SRI - component:COI Continuous: F02 Clock from 12 to 12 Grade = 1	000006
		4.4	SRI - component:WI Continuous: S03 Clock from 12 to 12 Grade = 1	000006
		9	RPP - component:WI Clock At 10 Remark = MISC MATERIAL	000014
		9	DAZ - component:WI Percent: 5 Clock At 2 Remark = DEBRIS Grade = 1	000014



Observation Images

Photo	Distance	Description	Time
	9.8	SRI - component:WI Continuous: F03 Clock from 12 to 12 Grade = 1	000015

Observations

Component	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
Chimney Interior	0.6	SRI	S01					12	12	
Chimney Interior	1	IWJ					True	4	5	
Chimney Interior	1.9	SRI	F01					12	12	
Cone Interior	2	SRI	S02					12	12	
Cone Interior	4.3	SRI	F02					12	12	
Wall Interior	4.4	SRI	S03					12	12	
Wall Interior	9	RPP						10		MISC MATERIAL
Wall Interior	9	DAZ				5		2		DEBRIS
Wall Interior	9.8	SRI	F03					12	12	

Pipe Connection Images

Photo	Number	Description	Depth	Clock
	1	Outgoing Connection Shape = Circle Height = 18 Pipe Condition = S Pipe Seal Condition = S Pipe type = GR	10.2	6
	2	Incoming Connection Shape = Circle Height = 18 Pipe Condition = S Pipe Seal Condition = S Pipe type = GR	10.1	9

Pipe Connections

Pipe No.	Clock	Rim to Invert	Direction	Material	Shape	Height (Dia.)	Condition	Seal Cond.	Pipe ID
1	6	10.2	O	PVC	Circular	18	S	S	
2	9	10.2	I	PVC	Circular	18	S	S	

Additional MACP Header Information

Media Label:		Evidence of Surcharge:	N
Work Order:		Northing:	
Sheet Number:		Easting:	
Date Cleaned:	Unknown	Elevation:	
Consequence of Failure		Coordinate System:	
Drainage Area:		Vertical Datum:	
Location Code:	D	GPS Accuracy:	
Inflow Potential		Additional Info:	
Location Details:		Imperial?:	True
Year Constructed:			
Year Renewed:			

Component: Cover

Cover Type Bolted:	False	Hole Diameter (Vent):	
Cover Type Gasketed:	False	Hole Number:	0
Cover Type Hatch (Double):	False	Cover Bearing Surface Diameter:	23
Cover Type Hatch (Single):	False	Cover Bearing Surface Width:	
Cover Type Inner Cover:	False	Cover Frame Fit:	G
Cover Type Lamphole:	False	Cover Condition Bolts Missing:	False
Cover Type Locking:	False	Cover Condition Broken:	False
Cover Type Removable Center:	False	Cover Condition Corroded (Pitted):	False
Cover Type Solid:	True	Cover Condition Cracked:	False
Cover Type Vented (Slots):	False	Cover Condition Missing:	False
Cover Shape:	C	Cover Condition Restraint Defective:	False
Cover Size:	24	Cover Condition Restraint Missing:	False
Center Cover Size:		Cover Condition Sound:	True
Cover Size Width:		Cover Insert Type:	N
Cover Material:	CAS		

Component: Cover Insert

Cover Insert Type	N
Insert Condition Cracked (Torn/Holes)	
Insert Condition Corroded (Pitted/Worn)	
Insert Condition Insert Fell	

Insert Condition Leaking	
Insert Condition Poorly Fitted:	
Insert Condition Sound:	

Component: Adjustment Ring

Adjustment Ring Type:	N
Adjustment Ring Material:	
Adjustment Ring Height:	
Ring Condition Broken:	
Ring Condition Corroded:	

Ring Condition Cracked	
Ring Condition Leaking:	
Ring Condition Poor Installation:	
Ring Condition Sound:	

Component: Frame

Frame Material:	CAS
Frame Bearing Surface Width:	0.5
Frame Bearing Surface Depth:	0.8
Frame Clear Open Diameter:	23
Frame Clear Open Width:	

Frame Condition Broken:	False
Frame Condition Coated:	False
Frame Condition Corroded (Pitted/Worn):	True
Frame Condition Cracked:	False
Frame Condition Missing:	False
Frame Condition Sound:	False

Component: Frame (continued)

Frame Offset Distance:	0
Frame Seal Inflow:	N
Frame Depth	0.5

Seal Condition Cracked:	False
Seal Condition Loose:	False
Seal Condition Offset:	False
Seal Condition Missing:	False
Seal Condition Sound:	True

Component: Chimney

Chimney Present:	Y
Chimney Material 1:	CR
Chimney Material 2:	
Chimney Inflow:	
Chimney Clear Opening:	

Chimney Depth:	1.9
Chimney Lining Interior:	
Chimney Lining Exterior:	
Chimney Condition:	

Component: Wall

Wall Diameter:	47.7
Wall by Size (Width)	
Wall Material	CR
Wall Depth	9.8

Wall Lining Interior	
Wall Lining Exterior:	
Wall Condition	

Component: Bench

Bench Present:	Y
Bench Material:	CN

Bench Lining:	C
Bench Condition:	

Component: Channel

Channel Installed:	N
Channel Material:	
Channel Type:	N

Channel Exposure:	
Channel Condition:	

Component: Steps

Number of Steps:	6
------------------	---

Step Material:	M
----------------	---

Additional Component Information

Notes:	
--------	--