

Project:		Date/Time:	June 28 2024 -
Street and City:	Silver St. & Miles - Marion	Weather:	Unknown Weather
Owner:		P.O. #	
Customer:		Inspection Status:	Remote Inspection
Surveyor Name and Certificate:	Dan Shrodes U-716-07004752	Inspection Level:	2
Reviewer Name and Certificate:	chad pauls P0036127-022022	MH:	MH12





Asset Details and Measurements

MH Use:	Combined	Access Type:	AMH
Rim to Invert:	16.5	Pre-Cleaning:	No Pre-Cleaning
Rim to Grade:	0	Purpose:	Maintenance related
Grade to Invert:	16.5	Surface Type:	Asphalt





MH Ratings

Overall Quick Rating: 312B			
Structural Quick Rating:	2B14	O&M Quick Rating:	3121
Overall MH Rating Index: 1.6			
Structural MH Rating Index:	1.8	O&M MH Rating Index:	1.3
Overall MH Rating: 53.0			
Structural MH Rating:	38.0	O&M MH Rating:	15.0




Observation Images

Photo	Distance	Description	Time
	0.8	SSC - component:CMI Clock from 12 to 12 Grade = 2	000004
	1	SSC - component:COI Clock from 12 to 12 Grade = 2	000004
	1.1	SSC - component:WI Continuous: S01 Clock from 12 to 12 Grade = 2	000005
	13.1	SSC - component:WI Continuous: F01 Clock from 12 to 12 Grade = 2	000018

Observation Images

	Photo	Distance	Description	Time
		13.4	SSC - component:WI Continuous: S02 Clock At 2 Grade = 2	000018
		13.4	OBB - component:WI Continuous: S03 Percent: 5 Clock At 8 Grade = 1	000018
		16	OBB - component:WI Continuous: F03 Percent: 5 Clock At 8 Grade = 1	000018
		16	SSC - component:WI Continuous: F02 Clock At 2 Grade = 2	000022

Observation Images

Photo	Distance	Description	Time
	16.1	DSZ - component:B Percent: 5 Clock At 6 Remark = DEBRIS Grade = 1	000021
	16.1	OBB - component:C Percent: 5 Clock At 8 Grade = 2	000021
	16.3	DSGV - component:C Percent: 10 Clock from 12 to 12 Grade = 1	000021




Observations

Component	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
Chimney Interior	0.8	SSC						12	12	
Cone Interior	1	SSC						12	12	
Wall Interior	1.1	SSC	S01					12	12	
Wall Interior	13.1	SSC	F01					12	12	
Wall Interior	13.4	SSC	S02					2		
Wall Interior	13.4	OBB	S03			5		8		
Wall Interior	16	OBB	F03			5		8		
Wall Interior	16	SSC	F02					2		
Bench	16.1	DSZ				5		6		DEBRIS

Observations

Component	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
Channel	16.1	OBB				5		8		
Channel	16.3	DSGV				10		12	12	

Pipe Connection Images

Photo	Number	Description	Depth	Clock
	3	Incoming Connection Shape = Circle Height = 12 Pipe Condition = D Pipe Seal Condition = S Pipe type = GR Comments = DSZ	10.5	5
	1	Outgoing Connection Shape = Circle Height = 69 Pipe Condition = S Pipe Seal Condition = S Pipe type = GR	16.5	6
	2	Incoming Connection Shape = Circle Height = 61 Pipe Condition = S Pipe Seal Condition = S Pipe type = GR	16.4	11

Pipe Connections

Pipe No.	Clock	Rim to Invert	Direction	Material	Shape	Height (Dia.)	Condition	Seal Cond.	Pipe ID
3	5	10.5	I	VCP	Circular	12	D	S	
1	6	10.5	O	VCP	Circular	69	S	S	
2	11	16.4	I	BR	Circular	61	S	S	

Additional MACP Header Information

Media Label:		Evidence of Surcharge:	N
Work Order:		Northing:	
Sheet Number:		Easting:	
Date Cleaned:	Unknown	Elevation:	
Consequence of Failure		Coordinate System:	
Drainage Area:		Vertical Datum:	
Location Code:	C	GPS Accuracy:	
Inflow Potential		Additional Info:	
Location Details:		Imperial?:	True
Year Constructed:			
Year Renewed:			

Component: Cover

Cover Type Bolted:	False	Hole Diameter (Vent):	A
Cover Type Gasketed:	False	Hole Number:	1
Cover Type Hatch (Double):	False	Cover Bearing Surface Diameter:	23
Cover Type Hatch (Single):	False	Cover Bearing Surface Width:	
Cover Type Inner Cover:	False	Cover Frame Fit:	G
Cover Type Lamphole:	False	Cover Condition Bolts Missing:	False
Cover Type Locking:	False	Cover Condition Broken:	False
Cover Type Removable Center:	False	Cover Condition Corroded (Pitted):	False
Cover Type Solid:	False	Cover Condition Cracked:	False
Cover Type Vented (Slots):	True	Cover Condition Missing:	False
Cover Shape:	C	Cover Condition Restraint Defective:	False
Cover Size:	24	Cover Condition Restraint Missing:	False
Center Cover Size:		Cover Condition Sound:	True
Cover Size Width:		Cover Insert Type:	N
Cover Material:	CAS		

Component: Cover Insert

Cover Insert Type	N
Insert Condition Cracked (Torn/Holes)	
Insert Condition Corroded (Pitted/Worn)	
Insert Condition Insert Fell	

Insert Condition Leaking	
Insert Condition Poorly Fitted:	
Insert Condition Sound:	

Component: Adjustment Ring

Adjustment Ring Type:	N
Adjustment Ring Material:	
Adjustment Ring Height:	
Ring Condition Broken:	
Ring Condition Corroded:	

Ring Condition Cracked	
Ring Condition Leaking:	
Ring Condition Poor Installation:	
Ring Condition Sound:	

Component: Frame

Frame Material:	CAS
Frame Bearing Surface Width:	0.5
Frame Bearing Surface Depth:	0.8
Frame Clear Open Diameter:	23
Frame Clear Open Width:	

Frame Condition Broken:	False
Frame Condition Coated:	False
Frame Condition Corroded (Pitted/Worn):	True
Frame Condition Cracked:	False
Frame Condition Missing:	False
Frame Condition Sound:	False

Component: Frame (continued)

Frame Offset Distance:	0
Frame Seal Inflow:	N
Frame Depth	0.7

Seal Condition Cracked:	False
Seal Condition Loose:	False
Seal Condition Offset:	False
Seal Condition Missing:	False
Seal Condition Sound:	True

Component: Chimney

Chimney Present:	Y
Chimney Material 1:	CR
Chimney Material 2:	
Chimney Inflow:	
Chimney Clear Opening:	

Chimney Depth:	0.9
Chimney Lining Interior:	XX
Chimney Lining Exterior:	
Chimney Condition:	

Component: Wall

Wall Diameter:	79.1
Wall by Size (Width)	
Wall Material	CR
Wall Depth	16

Wall Lining Interior	XX
Wall Lining Exterior:	
Wall Condition	

Component: Bench

Bench Present:	Y
Bench Material:	CN

Bench Lining:	
Bench Condition:	

Component: Channel

Channel Installed:	N
Channel Material:	
Channel Type:	N

Channel Exposure:	
Channel Condition:	

Component: Steps

Number of Steps:	10
------------------	----

Step Material:	M
----------------	---

Additional Component Information

Notes:	
--------	--