

Project:		Date/Time:	June 28 2024 -
Street and City:	Holland Rd. - Marion	Weather:	Unknown Weather
Owner:		P.O. #	
Customer:		Inspection Status:	Remote Inspection
Surveyor Name and Certificate:	Dan Shrodes U-716-07004752	Inspection Level:	2
Reviewer Name and Certificate:	Jessy Vargas-Bloom P0034044-102021	MH:	MH7





### Asset Details and Measurements

MH Use:	Combined	Access Type:	AMH
Rim to Invert:	13.9	Pre-Cleaning:	No Pre-Cleaning
Rim to Grade:	0	Purpose:	Maintenance related
Grade to Invert:	13.9	Surface Type:	ConcreteCollar





### MH Ratings

Overall Quick Rating: 483B			
Structural Quick Rating:	483A	O&M Quick Rating:	3421
Overall MH Rating Index: 2.7			
Structural MH Rating Index:	2.9	O&M MH Rating Index:	2.0
Overall MH Rating: 99.0			
Structural MH Rating:	81.0	O&M MH Rating:	18.0





### Observation Images

Photo	Distance	Description	Time
	0.7	SSC - component:CMI Continuous: S01 Clock from 12 to 12 Grade = 2	000005
	2.2	FM - component:CMI Clock from 3 to 4 Grade = 4	000007
	2.5	FL - component:CMI Clock At 5 Grade = 3	000008
	2.6	CM - component:CMI Clock from 12 to 1 Grade = 3	000010

### Observation Images





Photo	Distance	Description	Time
	2.7	SSC - component:CMI Continuous: F01 Clock from 12 to 12 Grade = 2	000010
	2.8	SSC - component:COI Clock from 12 to 12 Grade = 2	000011
	2.8	FM - component:COI Clock from 4 to 5 Grade = 4	000011
	2.8	FS - component:COI Clock from 12 to 1 Grade = 3	000011

Observation Images





Photo	Distance	Description	Time
	3	SSS - component:COI Clock At 10 Grade = 2	000011
	3.1	FL - component:COI Continuous: S02 Clock At 12 Grade = 3	000012
	3.3	FL - component:COI Clock At 10 Grade = 3	000012
	3.6	FM - component:COI Clock from 9 to 10 Grade = 4	000012







### Observation Images

Photo	Distance	Description	Time
	3.6	CL - component:COI Clock At 5 Grade = 2	000012
	4	FL - component:COI Continuous: S03 Clock At 5 Grade = 3	000013
	5.9	FL - component:COI Continuous: F02 Clock At 11 Grade = 3	000015
	6.3	FM - component:COI Clock from 12 to 1 Grade = 4	000016


### Observation Images

Photo	Distance	Description	Time
	7.1	FL - component:COI Continuous: F03 Clock At 5 Grade = 3	000017
	7.3	FM - component:COI Clock from 10 to 1 Grade = 4	000017
	7.3	FM - component:COI Clock from 4 to 7 Grade = 4	000017
	7.8	MML - component:COI Clock from 2 to 3 Grade = 4	000020

Observation Images

Photo	Distance	Description	Time
	8.9	MML - component:COI Clock At 4 Grade = 4	000022
	9.7	DB - component:COI Clock At 3 Grade = 3	000023
	10.1	IWB - component:C Clock from 1 to 5 Grade = 2	000023
	10.1	DAE - component:C Percent: 5 Clock from 7 to 11 Grade = 1	000023

### Observation Images

Photo	Distance	Description	Time
	13.9	DSC - component:C Percent: 30 Clock from 12 to 5 Grade = 3	000028



### Observations

Component	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
Chimney Interior	0.7	SSC	S01					12	12	
Chimney Interior	2.2	FM						3	4	
Chimney Interior	2.5	FL						5		
Chimney Interior	2.6	CM						12	1	
Chimney Interior	2.7	SSC	F01					12	12	
Cone Interior	2.8	SSC						12	12	
Cone Interior	2.8	FM						4	5	
Cone Interior	2.8	FS						12	1	
Cone Interior	3	SSS						10		




### Observations

Component	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
Cone Interior	3.1	FL	S02					12		
Cone Interior	3.3	FL						10		
Cone Interior	3.6	FM						9	10	
Cone Interior	3.6	CL						5		
Cone Interior	4	FL	S03					5		
Cone Interior	5.9	FL	F02					11		
Cone Interior	6.3	FM						12	1	
Cone Interior	7.1	FL	F03					5		
Cone Interior	7.3	FM						10	1	

### Observations

Component	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
Cone Interior	7.3	FM						4	7	
Cone Interior	7.8	MML						2	3	
Cone Interior	8.9	MML						4		
Cone Interior	9.7	DB						3		
Channel	10.1	IWB						1	5	
Channel	10.1	DAE				5		7	11	
Channel	13.9	DSC				30		12	5	

### Pipe Connection Images

Photo	Number	Description	Depth	Clock
	3	Incoming Connection Shape = Circle Height = 26 Pipe Condition = S Pipe Seal Condition = D Pipe type = GR Comments = COI-DB, MML	9.8	3
	1	Outgoing Connection Shape = Circle Height = 74 Pipe Condition = D Pipe Seal Condition = S Pipe type = GR Comments = DAE, IWB	13.9	6
	2	Incoming Connection Shape = Circle Height = 74 Pipe Condition = D Pipe Seal Condition = S Pipe type = GR Comments = DAE, IWB	13.8	12



## Pipe Connections

Pipe No.	Clock	Rim to Invert	Direction	Material	Shape	Height (Dia.)	Condition	Seal Cond.	Pipe ID
3	3	9.8	I	RCP	Circular	26	S	D	
1	6	9.8	O	RCP	Circular	74	D	S	
2	12	13.8	I	BR	Circular	74	D	S	

### Additional MACP Header Information

Media Label:		Evidence of Surcharge:	N
Work Order:		Northing:	
Sheet Number:		Easting:	
Date Cleaned:	Unknown	Elevation:	
Consequence of Failure		Coordinate System:	
Drainage Area:		Vertical Datum:	
Location Code:	C	GPS Accuracy:	
Inflow Potential		Additional Info:	
Location Details:		Imperial?:	True
Year Constructed:			
Year Renewed:			

### Component: Cover

Cover Type Bolted:	False	Hole Diameter (Vent):	A
Cover Type Gasketed:	False	Hole Number:	8
Cover Type Hatch (Double):	False	Cover Bearing Surface Diameter:	24
Cover Type Hatch (Single):	False	Cover Bearing Surface Width:	
Cover Type Inner Cover:	False	Cover Frame Fit:	G
Cover Type Lamphole:	False	Cover Condition Bolts Missing:	False
Cover Type Locking:	False	Cover Condition Broken:	False
Cover Type Removable Center:	False	Cover Condition Corroded (Pitted):	False
Cover Type Solid:	False	Cover Condition Cracked:	False
Cover Type Vented (Slots):	True	Cover Condition Missing:	False
Cover Shape:	C	Cover Condition Restraint Defective:	False
Cover Size:	24	Cover Condition Restraint Missing:	False
Center Cover Size:		Cover Condition Sound:	True
Cover Size Width:		Cover Insert Type:	N
Cover Material:	CAS		

### Component: Cover Insert

Cover Insert Type	N
Insert Condition Cracked (Torn/Holes)	
Insert Condition Corroded (Pitted/Worn)	
Insert Condition Insert Fell	

Insert Condition Leaking	
Insert Condition Poorly Fitted:	
Insert Condition Sound:	

### Component: Adjustment Ring

Adjustment Ring Type:	N
Adjustment Ring Material:	
Adjustment Ring Height:	
Ring Condition Broken:	
Ring Condition Corroded:	

Ring Condition Cracked	
Ring Condition Leaking:	
Ring Condition Poor Installation:	
Ring Condition Sound:	

### Component: Frame

Frame Material:	CAS
Frame Bearing Surface Width:	0.5
Frame Bearing Surface Depth:	0.8
Frame Clear Open Diameter:	23
Frame Clear Open Width:	

Frame Condition Broken:	False
Frame Condition Coated:	False
Frame Condition Corroded (Pitted/Worn):	True
Frame Condition Cracked:	False
Frame Condition Missing:	False
Frame Condition Sound:	False



### Component: Frame (continued)

Frame Offset Distance:	0
Frame Seal Inflow:	N
Frame Depth	

Seal Condition Cracked:	False
Seal Condition Loose:	False
Seal Condition Offset:	False
Seal Condition Missing:	True
Seal Condition Sound:	False

### Component: Chimney

Chimney Present:	Y
Chimney Material 1:	BR
Chimney Material 2:	
Chimney Inflow:	
Chimney Clear Opening:	

Chimney Depth:	2.7
Chimney Lining Interior:	C
Chimney Lining Exterior:	
Chimney Condition:	

### Component: Wall

Wall Diameter:	74
Wall by Size (Width)	
Wall Material	BR
Wall Depth	10

Wall Lining Interior	
Wall Lining Exterior:	
Wall Condition	

### Component: Bench

Bench Present:	N
Bench Material:	

Bench Lining:	
Bench Condition:	

### Component: Channel

Channel Installed:	Y
Channel Material:	BR
Channel Type:	F

Channel Exposure:	F
Channel Condition:	

### Component: Steps

Number of Steps:	4
------------------	---

Step Material:	M
----------------	---

### Additional Component Information

Notes:	
--------	--