

Inspection Marion County, Ohio

US Manhole 5


DS Manhole 4A

Inspected October 3, 2024

Platform Aerial Drone


Sensor 3D Lidar


Report Date October 29, 2024




































































INSPECTION HEADER

DATE: 10/3/2024

PIPE SEG REF. MH 5 - MA 4A

UP MH: MH 5 **DOWN MH: MH 4A**

SUMMARY

Inspection Date

Pipe Segment Reference

Surveyed By

Certificate Number

10/3/2024 12:00 AM

MH 5 - MA 4A

SHAWN DUNNELL

U-915-70001437

Project

Street

Upstream MH

Downstream MH MH 4A

2420053PW

HOLLAND RD

MH 5

Length Surveyed (ft)

Direction Upstream

Pre-Cleaning No Pre-Cleaning **Total Length (ft)**

179.6

ASSET

72

Height (mm)

Shape Circular

Material BR

Pipe Use

Combined Pipe

PROJECT

Owner

Customer

CITY OF MARION

CT CONSULTANTS

INSPECTION

12:00 AM

Inspection Time

City MARION **Inspection Status**

CI

In Feet (Imperial)

Yes






SMART DIAGRAM

DATE: 10/3/2024

PIPE SEG REF. MH 5 - MA 4A

UP MH: MH 5 DOWN MH: MH 4A





OBSERVATIONS

DATE: 10/3/2024

PIPE SEG REF. MH 5 - MA 4A

UP MH: MH 5 DOWN MH: MH 4A

Dist	Time	Description	Code	Clock	Dim. 1	Dim. 2	%	Remarks	Cont.	Grade
0	0:05	Manhole	A l M	-	-	-	-	MH 4A	-	-
0	0:05	Miscellaneous Water Le vel	MLW	-	-	-	5	-	-	-
0	0:05	Miscellaneous General Observatio	MOG	-	-	-	-	10.1 FT OFFSE T	-	-
1	0:23	Missing Mortar Small	MBM		-	-	-	-	S01	2
1	0:31	Miscellaneous General Observatio	MOG	-	-	-	-	DAE LESS THA N 5%	-	-
50.9	1:03	Infiltration Weeper Barr el	IWB		-	-	-	-	-	2
58.4	1:07	Infiltration Stain Barrel	ISB		-	-	-	-	-	1
64	1:10	Infiltration Weeper Barr el	IWB		-	-	-	-	-	2
73.6	1:15	Infiltration Weeper Barr el	IWB		-	-	-	-	-	2
179	1:59	Missing Mortar Small	MBM		-	-	-	-	F01	2
179.6	1:59	Manhole	AHM	-	-	-	-	MH 5	-	-




OBSERVATION SNAPSHOTS

DATE: 10/3/2024

PIPE SEG REF. MH 5 - MA 4A

UP MH: MH 5 DOWN MH: MH 4A










0 ft



0 ft

MMS (2) 5 - 7:00 1 ft









MGO 1 ft

IWB 4 - 5:00 50.9 ft

(ISB) 4 - 5:00 58.4 ft

(2) IWB 64 ft 4:00







2 IWB 73.6 ft 4 - 5:00

2 MMS 179 ft 5 - 7:00

179.6 ft



RATINGS

DATE: 10/3/2024

PIPE SEG REF. MH 5 - MA 4A

UP MH: MH 5 DOWN MH: MH 4A

PIPE RATING INDEX

Overall (2)

Structural

0&M

2 (1.8)

Sum of all graded conditions divided by the total number of conditions. 0-5 scale.

PIPE RATING

Overall 79 Structural 72

O&M

7

Sum of all graded conditions.

QUICK RATING

Overall 2 F 1 1

Structural 2 F 0 0

O&M2 3 1 1

Likelihood of Failure

First digit is highest graded condition. Second digit is count of those conditions (A = 10-14, B = 15-19, etc.). Third digit is second-highest graded condition. Fourth digit is count of those conditions. LoF is Quick Rating divided by 10 (scale from 0-6).

FREQUENCY OF CONDITION GRADES

Grade # **1 2** 1 5

3 0

4 0

5

Count of each condition grade in the inspection.