

Pipe Details and Measurements

Pipe Ratings

Total Length:


1

BOARDMAN — September 26 2023	Up MH: BO657.02
Pipe: BO657.02-BO657.01	Down MH: BO657.01


Observations & Defects

Surveyed Length: 291.4

Total Length: 291.4

Flow Direction: 

Survey Direction:
Downstream







BOARDMAN — September 26 2023

Up MH: BO657.02

Pipe: BO657.02-BO657.01

Down MH: BO657.01





Photo	Distance	Description	Time
	0	AMH - Manhole Remark = BO657.02	00:00:21
	0	MWL - Miscellaneous Water Level Percent: 5	00:00:35
	104.8	MWL - Miscellaneous Water Level Percent: 20	00:03:15
	149.3	MWL - Miscellaneous Water Level Percent: 35	00:04:44

BOARDMAN — September 26 2023

Up MH: BO657.02

Pipe: BO657.02-BO657.01



Down MH: BO657.01

Photo	Distance	Description	Time
	161.1	MWLS - Miscellaneous Water Level Sag Continuous: S01 Percent: 40 Grade = 3	00:05:22
	197.3	MWLS - Miscellaneous Water Level Sag Continuous: F01 Percent: 40 Grade = 3	00:06:27
	201.3	LD - Line Down Percent: 5 Grade = 1	00:06:50
	203.9	MWL - Miscellaneous Water Level Percent: 5	00:07:01

ARE WE SUGGESTING TO REPLACE THIS 40-LF OF SEWER, PRIOR TO LINING?



BOARDMAN — September 26 2023	Up MH: BO657.02
Pipe: BO657.02-BO657.01	Down MH: BO657.01

Photo	Distance	Description	Time
	257.3	DAE - Deposits Attached Encrustation Percent: 5 Joint: True Clock from 7 to 5 Grade = 2 May be able to address with heavy cleaning, check spec	00:08:21
	291.4	AMH - Manhole Remark = BO657.01	00:09:41

BOARDMAN — September 26 2023

Up MH: BO657.02

Pipe: BO657.02-BO657.01

Down MH: BO657.01

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:00:21	0	AMH								BO657.02
00:00:35	0	MWL				5				
00:03:15	104.8	MWL				20				
00:04:44	149.3	MWL				35				
00:05:22	161.1	MWL S	S01			40				
00:06:27	197.3	MWL S	F01			40				
00:06:27	201.3	LD				5				
00:07:01	203.9	MWL				5				
00:08:21	257.3	DAE				5	True	7	5	

BOARDMAN — September 26 2023	Up MH: BO657.02
Pipe: BO657.02-BO657.01	Down MH: BO657.01

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:09:41	291.4	AMH								BO657.01

BOARDMAN — September 26 2023

Up MH: BO657.02

Pipe: BO657.02-BO657.01

Down MH: BO657.01

Additional PACP Header Information

Media Label:		Up Rim to Invert:	
Work Order:		Up Rim to Grade:	
Sheet Number:		Up Grade to Invert:	
Date Cleaned:	Unknown	Up Northing:	
Flow Control:		Up Easting:	
Consequence of Failure		Up Elevation:	
Pressure Value:		Down Rim to Invert:	
Drainage Area:		Down Rim to Grade:	
Location Code:	D	Down Grade to Invert:	
Location Details:		Down Northing:	
Coating Method:		Down Easting:	
Pipe Joint Length:		Down Elevation:	
Year Constructed:		Coordinate System:	
Year Renewed:		Vertical Datum:	
		GPS Accuracy:	
Reverse Setup:	0	Imperial?:	True