

Project:	2320059	Date/Time:	September 26 2023 - 11:43
Street and City:	PIERCE DR - BOARDMAN	Weather:	Dry - No precipitation during survey
Owner:	CITY OF BOARDMAN	Inspection Status:	Complete Inspection
Customer:	ABC WATER	Segment:	BO657.04-BO657.03
Surveyor Name and Certificate:	SHAWN DUNNELL 915-70001437	Direction:	Downstream
Reviewer Name and Certificate:		Up MH:	BO657.04
P.O. #		Down MH:	B0657.03

Pipe Details and Measurements

Pipe Use:	SW	Material:	RCP
Height:	12	Lining:	
Width:		Joint Length:	
Shape:	C	Purpose:	F
Pre-Cleaning:	No Pre-Cleaning	Additional Info:	

Pipe Ratings

Overall Quick Rating: 4213

Structural Quick Rating:	4100	O&M Quick Rating:	4113
Structural Pipe Rating Index:	4.0	O&M Pipe Rating Index:	1.8



Surveyed Length: 30

Total Length:


Inspection Technology Used: CCTV

BOARDMAN — September 26 2023	Up MH: BO657.04
Pipe: BO657.04-BO657.03	Down MH: B0657.03


Observations & Defects

Surveyed Length: 30

Total Length: 30

Flow Direction: 

Survey Direction:
Downstream







BOARDMAN — September 26 2023

Up MH: BO657.04

Pipe: BO657.04-BO657.03

Down MH: B0657.03

Photo	Distance	Description	Time
	0	AMH - Manhole Remark = BO657.04	00:00:24
	0	MWL - Miscellaneous Water Level	00:00:42
	19.8	IR - Infiltration Runner Joint: True Clock from 10 to 2 Grade = 4	00:02:05
	21.1	RFJ - Roots Fine Joint Joint: True Clock At 12 Grade = 1	00:02:21

BOARDMAN — September 26 2023


Up MH: B0657.04

Pipe: B0657.04-B0657.03

Down MH: B0657.03

Photo	Distance	Description	Time
	25.6	LR - Line Right Percent: 5 Grade = 1	00:02:42
	25.6	JOL - Joint Offset Large Grade = 4	00:02:44
	30	MMC - Miscellaneous Material Change Remark = RCP TO VCP	00:04:42
	30	LD - Line Down Percent: 10 Grade = 1	00:05:09

BOARDMAN — September 26 2023	Up MH: BO657.04
Pipe: BO657.04-BO657.03	Down MH: B0657.03

Photo	Distance	Description	Time
	30	MSA - Miscellaneous Survey Abandoned Remark = LIND DOWN AND OFFSET JOINTS	00:05:41

BOARDMAN — September 26 2023

Up MH: BO657.04

Pipe: BO657.04-BO657.03

Down MH: B0657.03

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:00:24	0	AMH								BO657.04
00:00:42	0	MWL				0				
00:02:05	19.8	IR					True	10	2	
00:02:21	21.1	RFJ					True	12		
00:02:42	25.6	LR				5				
00:02:44	25.6	JOL								
00:02:44	30	MMC								RCP TO VCP
00:05:09	30	LD				10				
00:05:41	30	MSA								LIND DOWN AND OFFSET JOINTS

BOARDMAN — September 26 2023

Up MH: BO657.04

Pipe: BO657.04-BO657.03

Down MH: B0657.03

Additional PACP Header Information

Media Label:		Up Rim to Invert:	
Work Order:		Up Rim to Grade:	
Sheet Number:		Up Grade to Invert:	
Date Cleaned:	Unknown	Up Northing:	
Flow Control:		Up Easting:	
Consequence of Failure		Up Elevation:	
Pressure Value:		Down Rim to Invert:	
Drainage Area:		Down Rim to Grade:	
Location Code:	D	Down Grade to Invert:	
Location Details:		Down Northing:	
Coating Method:		Down Easting:	
Pipe Joint Length:		Down Elevation:	
Year Constructed:		Coordinate System:	
Year Renewed:		Vertical Datum:	
		GPS Accuracy:	
Reverse Setup:	0	Imperial?:	True