

Project:	2320059	Date/Time:	September 26 2023 - 14:26
Street and City:	PIERCE DR - BOARDMAN	Weather:	Dry - No precipitation during survey
Owner:	CITY OF BOARDMAN	Inspection Status:	Complete Inspection
Customer:	ABC WATER	Segment:	BO657.06-BO657.05
Surveyor Name and Certificate:	SHAWN DUNNELL 915-70001437	Direction:	Downstream
Reviewer Name and Certificate:		Up MH:	BO657.06
P.O. #		Down MH:	BO657.05

### Pipe Details and Measurements

Pipe Use:	SW	Material:	RPM
Height:	10	Lining:	
Width:		Joint Length:	
Shape:	C	Purpose:	F
Pre-Cleaning:	No Pre-Cleaning	Additional Info:	

### Pipe Ratings

**Overall Quick Rating: 5121**

Structural Quick Rating:	5100	O&M Quick Rating:	2113
Structural Pipe Rating Index:	5.0	O&M Pipe Rating Index:	1.3



Surveyed Length: 30

Total Length:

Inspection Technology Used: CCTV

BOARDMAN — September 26 2023

Up MH: BO657.06

Pipe: BO657.06-BO657.05


Down MH: BO657.05

### Observations & Defects


Surveyed Length: 30

Total Length: 30

Flow Direction:



Survey Direction:  
Downstream







BOARDMAN — September 26 2023

Up MH: BO657.06

Pipe: BO657.06-BO657.05

Down MH: BO657.05

Photo	Distance	Description	Time
	0	AMH - Manhole Remark = BO657.06	00:00:27
	0	MWL - Miscellaneous Water Level Percent: 15	00:00:58
	2	MMC - Miscellaneous Material Change Remark = PLASTIC TO RCP	00:01:10
	2	DSGV - Deposits Settled Gravel Continuous: S01 Percent: 10 Clock from 5 to 7 Grade = 2	00:01:22

BOARDMAN — September 26 2023

Up MH: BO657.06

Pipe: BO657.06-BO657.05

Down MH: BO657.05


Photo	Distance	Description	Time
	8	DSGV - Deposits Settled Gravel Continuous: F01 Percent: 10 Clock from 5 to 7 Grade = 2	00:03:49
	13.7	LD - Line Down Continuous: S02 Percent: 5 Grade = 1	00:04:07
	25.7	HWV - Hole Void Visible Joint: True Clock from 5 to 7 Grade = 5	00:04:53
	30	LD - Line Down Continuous: F02 Percent: 5 Grade = 1	00:05:37

BOARDMAN — September 26 2023

Up MH: BO657.06

Pipe: BO657.06-BO657.05

Down MH: BO657.05

Photo	Distance	Description	Time
	<p>30</p>	<p>ACB - Access Point Catch Basin          Remark = BO657.05</p>	<p>00:05:44</p>

BOARDMAN — September 26 2023

Up MH: BO657.06

Pipe: BO657.06-BO657.05

Down MH: BO657.05

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:00:27	0	AMH								BO657.06
00:00:58	0	MWL				15				
00:01:10	2	MMC								PLASTIC TO RCP
00:01:22	2	DSG V	S01			10		5	7	
00:03:49	8	DSG V	F01			10		5	7	
00:04:07	13.7	LD	S02			5				
00:04:07	25.7	HVV					True	5	7	
00:05:37	30	LD	F02			5				
00:05:44	30	ACB								BO657.05

BOARDMAN — September 26 2023

Up MH: BO657.06

Pipe: BO657.06-BO657.05

Down MH: BO657.05

### Additional PACP Header Information

Media Label:		Up Rim to Invert:	
Work Order:		Up Rim to Grade:	
Sheet Number:		Up Grade to Invert:	
Date Cleaned:	Unknown	Up Northing:	
Flow Control:		Up Easting:	
Consequence of Failure		Up Elevation:	
Pressure Value:		Down Rim to Invert:	
Drainage Area:		Down Rim to Grade:	
Location Code:	D	Down Grade to Invert:	
Location Details:		Down Northing:	
Coating Method:		Down Easting:	
Pipe Joint Length:		Down Elevation:	
Year Constructed:		Coordinate System:	
Year Renewed:		Vertical Datum:	
		GPS Accuracy:	
Reverse Setup:	0	Imperial?:	True