

Project:	2320059	Date/Time:	September 26 2023 - 12:34
Street and City:	MILL TRACE RD - BOARDMAN	Weather:	Dry - No precipitation during survey
Owner:	CITY OF BOARDMAN	Inspection Status:	Complete Inspection
Customer:	ABC WATER	Segment:	BO657.11-BO657.11A
Surveyor Name and Certificate:	SHAWN DUNNELL 915-70001437	Direction:	Upstream
Reviewer Name and Certificate:		Up MH:	BO657.11
P.O. #		Down MH:	B0657.11A

Pipe Details and Measurements

Pipe Use:	SW	Material:	RCP
Height:	15	Lining:	
Width:		Joint Length:	
Shape:	C	Purpose:	F
Pre-Cleaning:	No Pre-Cleaning	Additional Info:	

Pipe Ratings

Overall Quick Rating: 3125

Structural Quick Rating:	3122	O&M Quick Rating:	2300
Structural Pipe Rating Index:	2.3	O&M Pipe Rating Index:	2.0



Surveyed Length: 140.5

Total Length:


Inspection Technology Used: CCTV

BOARDMAN — September 26 2023	Up MH: B0657.11
Pipe: B0657.11-B0657.11A	Down MH: B0657.11A


Observations & Defects

Surveyed Length: 140.5

Total Length: 140.5

Flow Direction: 

Survey Direction:
Upstream







BOARDMAN — September 26 2023

Up MH: B0657.11

Pipe: B0657.11-B0657.11A

Down MH: B0657.11A





Photo	Distance	Description	Time
 A top-down view of a manhole opening. The interior of the manhole is visible, showing a circular structure with a grid of bars. The walls are made of concrete blocks. A small blue label in the bottom left corner reads "0.0 ft".	0	AMH - Manhole Remark = B0657.11A	00:00:24
 A view looking down into a pipe. The water level is visible, and the pipe walls are made of concrete. A small blue label in the bottom left corner reads "0.0 ft".	0	MWL - Miscellaneous Water Level	00:00:39
 A view of a crack in the pipe wall. The crack is longitudinal and runs along the length of the pipe. The walls are made of concrete. A small blue label in the bottom left corner reads "50.0 ft".	50	CL - Crack Longitudinal Continuous: S01 Joint: True Clock At 12 Grade = 2	00:02:01
 A view of a fracture in the pipe wall. The fracture is longitudinal and runs along the length of the pipe. The walls are made of concrete. A small blue label in the bottom left corner reads "52.2 ft".	52.2	FL - Fracture Longitudinal Joint: True Clock At 6 Grade = 3	00:02:18

BOARDMAN — September 26 2023


Up MH: B0657.11

Pipe: B0657.11-B0657.11A

Down MH: B0657.11A

Photo	Distance	Description	Time
	55.7	CL - Crack Longitudinal Continuous: F01 Joint: True Clock At 12 Grade = 2	00:02:33
	62.5	CL - Crack Longitudinal Joint: True Clock At 12 Grade = 2	00:02:57
	107.2	DSGV - Deposits Settled Gravel Continuous: S02 Percent: 5 Clock At 6 Grade = 2	00:04:12
	122.9	DSGV - Deposits Settled Gravel Continuous: F02 Percent: 5 Clock At 6 Grade = 2	00:04:41

BOARDMAN — September 26 2023	Up MH: BO657.11
Pipe: BO657.11-BO657.11A	Down MH: B0657.11A

Photo	Distance	Description	Time
 <div><div>Date: 09/26/2023 12:40</div><div>City: BOARDMAN</div><div>Pipe Deg. Ref: BO657.11-BO657.11A</div><div>Up MH: BO657.11</div><div>Down MH: B0657.11A</div><div>Direction: U</div><div>140.5 ft</div></div>	140.5	AMH - Manhole Remark = BO657.11	00:05:52

BOARDMAN — September 26 2023

Up MH: B0657.11

Pipe: B0657.11-B0657.11A

Down MH: B0657.11A

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:00:24	0	AMH								B0657.11A
00:00:39	0	MWL				0				
00:02:01	50	CL	S01				True	12		
00:02:18	52.2	FL					True	6		
00:02:33	55.7	CL	F01				True	12		
00:02:57	62.5	CL					True	12		
00:02:57	107.2	DSG V	S02			5		6		
00:04:41	122.9	DSG V	F02			5		6		
00:05:52	140.5	AMH								B0657.11

BOARDMAN — September 26 2023

Up MH: BO657.11

Pipe: BO657.11-BO657.11A

Down MH: B0657.11A

Additional PACP Header Information

Media Label:		Up Rim to Invert:	
Work Order:		Up Rim to Grade:	
Sheet Number:		Up Grade to Invert:	
Date Cleaned:	Unknown	Up Northing:	
Flow Control:		Up Easting:	
Consequence of Failure		Up Elevation:	
Pressure Value:		Down Rim to Invert:	
Drainage Area:		Down Rim to Grade:	
Location Code:	D	Down Grade to Invert:	
Location Details:		Down Northing:	
Coating Method:		Down Easting:	
Pipe Joint Length:		Down Elevation:	
Year Constructed:		Coordinate System:	
Year Renewed:		Vertical Datum:	
		GPS Accuracy:	
Reverse Setup:	0	Imperial?:	True