

Project:	2320059	Date/Time:	September 26 2023 - 10:40
Street and City:	PIERCE DR - BOARDMAN	Weather:	Unknown Weather
Owner:	CITY OF BOARDMAN	Inspection Status:	Complete Inspection
Customer:	ABC WATER	Segment:	BO657.11A-BO657.09
Surveyor Name and Certificate:	SHAWN DUNNELL 915-70001437	Direction:	Upstream
Reviewer Name and Certificate:		Up MH:	BO657.11A
P.O. #		Down MH:	BO357.09


Pipe Details and Measurements

Pipe Use:	SW	Material:	RCP
Height:	15	Lining:	
Width:		Joint Length:	
Shape:	C	Purpose:	F
Pre-Cleaning:	No Pre-Cleaning	Additional Info:	

Pipe Ratings

Overall Quick Rating: 412A

Structural Quick Rating:	412A	O&M Quick Rating:	2100
Structural Pipe Rating Index:	2.2	O&M Pipe Rating Index:	2.0



Surveyed Length: 169.8 Total Length:


Inspection Technology Used: CCTV

BOARDMAN — September 26 2023	Up MH: BO657.11A
Pipe: BO657.11A-BO657.09	Down MH: BO357.09


Observations & Defects

Surveyed Length: 169.8

Total Length: 169.8

Flow Direction: 

Survey Direction:
Upstream







BOARDMAN — September 26 2023

Up MH: BO657.11A

Pipe: BO657.11A-BO657.09

Down MH: BO357.09





Photo	Distance	Description	Time
	0	AMH - Manhole Remark = BO357.09	00:00:28
	0	MWL - Miscellaneous Water Level Percent: 20	00:00:43
	20	CL - Crack Longitudinal Joint: True Clock At 12 Grade = 2	00:02:29
	24	CL - Crack Longitudinal Continuous: S01 Clock At 12 Grade = 2	00:03:04

BOARDMAN — September 26 2023



Up MH: BO657.11A

Pipe: BO657.11A-BO657.09

Down MH: BO357.09

Photo	Distance	Description	Time
	24	MWL - Miscellaneous Water Level Percent: 30	00:03:18
	67.3	CL - Crack Longitudinal Continuous: F01 Clock At 12 Grade = 2	00:04:37
	67.3	MWL - Miscellaneous Water Level Percent: 15	00:04:41
	83.7	JOL - Joint Offset Large Grade = 4	00:05:19

BOARDMAN — September 26 2023	Up MH: BO657.11A
Pipe: BO657.11A-BO657.09	Down MH: BO357.09

Photo	Distance	Description	Time
 <p>121.5 ft</p>	121.5	OBN - Obstruction Construction Debris Percent: 5 Clock At 6 Remark = ROD Grade = 2	00:06:21
 <p>169.8 ft</p>	169.8	AMH - Manhole Remark = BO657.11A	00:08:12

BOARDMAN — September 26 2023

Up MH: BO657.11A

Pipe: BO657.11A-BO657.09

Down MH: BO357.09

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:00:28	0	AMH								BO357.09
00:00:43	0	MWL				20				
00:02:29	20	CL					True	12		
00:03:04	24	CL	S01					12		
00:03:18	24	MWL				30				
00:04:37	67.3	CL	F01					12		
00:04:37	67.3	MWL				15				
00:05:19	83.7	JOL								
00:06:21	121.5	OBN				5		6		ROD

BOARDMAN — September 26 2023	Up MH: BO657.11A
Pipe: BO657.11A-BO657.09	Down MH: BO357.09

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:08:12	169.8	AMH								BO657.11A

BOARDMAN — September 26 2023

Up MH: BO657.11A

Pipe: BO657.11A-BO657.09

Down MH: BO357.09

Additional PACP Header Information

Media Label:		Up Rim to Invert:	
Work Order:		Up Rim to Grade:	
Sheet Number:		Up Grade to Invert:	
Date Cleaned:	Unknown	Up Northing:	
Flow Control:		Up Easting:	
Consequence of Failure		Up Elevation:	
Pressure Value:		Down Rim to Invert:	
Drainage Area:		Down Rim to Grade:	
Location Code:	D	Down Grade to Invert:	
Location Details:		Down Northing:	
Coating Method:		Down Easting:	
Pipe Joint Length:		Down Elevation:	
Year Constructed:		Coordinate System:	
Year Renewed:		Vertical Datum:	
		GPS Accuracy:	
Reverse Setup:	0	Imperial?:	True