

Project:	2320059	Date/Time:	September 26 2023 - 12:41
Street and City:	MILL TRACE RD - BOARDMAN	Weather:	Dry - No precipitation during survey
Owner:	CITY OF BOARDMAN	Inspection Status:	Complete Inspection
Customer:	ABC WATER	Segment:	BO657.15-BO657.11
Surveyor Name and Certificate:	SHAWN DUNNELL 915-70001437	Direction:	Upstream
Reviewer Name and Certificate:		Up MH:	BO657.15
P.O. #		Down MH:	BO657.11

Pipe Details and Measurements

Pipe Use:	SW	Material:	RCP
Height:	18	Lining:	
Width:		Joint Length:	
Shape:	C	Purpose:	F
Pre-Cleaning:	No Pre-Cleaning	Additional Info:	

Pipe Ratings

Overall Quick Rating: 4231

Structural Quick Rating:	0000	O&M Quick Rating:	4231
Structural Pipe Rating Index:	0.0	O&M Pipe Rating Index:	3.3



Surveyed Length: 33

Total Length:


Inspection Technology Used: CCTV

BOARDMAN — September 26 2023	Up MH: BO657.15
Pipe: BO657.15-BO657.11	Down MH: BO657.11


Observations & Defects

Surveyed Length: 33

Total Length: 33

Flow Direction: 

Survey Direction:
Upstream






BOARDMAN — September 26 2023

Up MH: BO657.15

Pipe: BO657.15-BO657.11

Down MH: BO657.11





Photo	Distance	Description	Time
	0	AMH - Manhole Remark = BO657.11	00:00:20
	0	MWL - Miscellaneous Water Level	00:00:44
	2.4	OBR - Obstruction Rocks Continuous: S01 Percent: 15 Clock from 4 to 8 Grade = 3	00:00:55
	9.6	OBR - Obstruction Rocks Continuous: F01 Percent: 15 Clock from 4 to 8 Grade = 3	00:01:43

BOARDMAN — September 26 2023

Up MH: BO657.15

Pipe: BO657.15-BO657.11

Down MH: BO657.11

Photo	Distance	Description	Time
	9.6	DSF - Deposits Settled Fine Percent: 5 Clock from 5 to 7 Grade = 2	00:01:46
	22.6	DSC - Deposits Settled Hard/Compacted Continuous: S02 Percent: 25 Clock from 4 to 8 Grade = 4	00:02:27
	33	DSC - Deposits Settled Hard/Compacted Continuous: F02 Percent: 25 Clock from 4 to 8 Grade = 4	00:03:03
	33	ACB - Access Point Catch Basin Remark = BO657.15	00:03:24

BOARDMAN — September 26 2023

Up MH: BO657.15

Pipe: BO657.15-BO657.11

Down MH: BO657.11

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:00:20	0	AMH								BO657.11
00:00:44	0	MWL				0				
00:00:55	2.4	OBR	S01			15		4	8	
00:01:43	9.6	OBR	F01			15		4	8	
00:01:46	9.6	DSF				5		5	7	
00:02:27	22.6	DSC	S02			25		4	8	
00:02:27	33	DSC	F02			25		4	8	
00:03:24	33	ACB								BO657.15

BOARDMAN — September 26 2023

Up MH: BO657.15

Pipe: BO657.15-BO657.11

Down MH: BO657.11

Additional PACP Header Information

Media Label:		Up Rim to Invert:	
Work Order:		Up Rim to Grade:	
Sheet Number:		Up Grade to Invert:	
Date Cleaned:	Unknown	Up Northing:	
Flow Control:		Up Easting:	
Consequence of Failure		Up Elevation:	
Pressure Value:		Down Rim to Invert:	
Drainage Area:		Down Rim to Grade:	
Location Code:	D	Down Grade to Invert:	
Location Details:		Down Northing:	
Coating Method:		Down Easting:	
Pipe Joint Length:		Down Elevation:	
Year Constructed:		Coordinate System:	
Year Renewed:		Vertical Datum:	
		GPS Accuracy:	
Reverse Setup:	0	Imperial?:	True