

Project:	2420009	Date/Time:	January 31 2024 - 10:02
Street and City:	TURNBERRY DR - YOUNGSTOWNE	Weather:	Dry Weather/Wet Ground
Owner:	CITY OF BOARDMAN	Inspection Status:	Complete Inspection
Customer:	ABC WATER	Segment:	MY00001_P1_M01-MY00001_P1_M02
Surveyor Name and Certificate:	SHAWN DUNNELL U-915-70001437	Direction:	Downstream
Reviewer Name and Certificate:		Up MH:	MY00001_P1_M01
P.O. #		Down MH:	MY00001_P1_M02

Pipe Details and Measurements

Pipe Use:	SW	Material:	RCP
Height:	42	Lining:	
Width:		Joint Length:	
Shape:	C	Purpose:	F
Pre-Cleaning:	Heavy Cleaning	Additional Info:	

Pipe Ratings

Overall Quick Rating: 4232

Structural Quick Rating:	4121	O&M Quick Rating:	4132
Structural Pipe Rating Index:	3.0	O&M Pipe Rating Index:	2.5



Surveyed Length: 99.6

Total Length:

Inspection Technology Used: CCTV

YOUNGSTOWNE — January 31 2024

Up MH: MY00001_P1_M01

Pipe: MY00001_P1_M01-MY00001_P1_M02


Down MH: MY00001_P1_M02

Observations & Defects


Surveyed Length: 99.6

Total Length: 99.6

Flow Direction:



Survey Direction:
Downstream







YOUNGSTOWNE — January 31 2024

Up MH: MY00001_P1_M01

Pipe: MY00001_P1_M01-MY00001_P1_M02

Down MH: MY00001_P1_M02





Photo	Distance	Description	Time
 <p>00:00:10</p>	0	AMH - Manhole Remark = MY00001_P1_M01	00:00:10
 <p>00:00:40</p>	0	MWL - Miscellaneous Water Level Percent: 5	00:00:40
 <p>00:01:17</p>	18.3	ISJ - Infiltration Stain Joint Joint: True Clock At 12 Grade = 1	00:01:17
 <p>00:02:07</p>	33.6	FC - Fracture Circumferential Joint: True Clock from 8 to 9 Grade = 2	00:02:07

YOUNGSTOWNE — January 31 2024

Up MH: MY00001_P1_M01

Pipe: MY00001_P1_M01-MY00001_P1_M02

Down MH: MY00001_P1_M02




Photo	Distance	Description	Time
	49.2	IR - Infiltration Runner Joint: True Clock from 9 to 3 Grade = 4	00:03:21
	49.2	DAE - Deposits Attached Encrustation Percent: 5 Joint: True Clock from 7 to 5 Grade = 2	00:03:27
	64.2	DAE - Deposits Attached Encrustation Percent: 5 Clock from 7 to 9 Grade = 2	00:03:21
	64.2	TBI - Tap Break-in Intruding Measurement 1: 10 Measurement 2: 5 Clock At 10 Grade = 3	00:03:58

YOUNGSTOWNE — January 31 2024

Up MH: MY00001_P1_M01

Pipe: MY00001_P1_M01-MY00001_P1_M02

Down MH: MY00001_P1_M02

Photo	Distance	Description	Time
	80.7	B - Broken Joint: True Clock from 4 to 5 Grade = 4	00:05:21
	80.7	ID - Infiltration Dripper Joint: True Clock At 5 Grade = 3	00:05:35
	99.6	AMH - Manhole Remark = MY00001_P1_M02	00:06:49

YOUNGSTOWNE — January 31 2024

Up MH: MY00001_P1_M01

Pipe: MY00001_P1_M01-MY00001_P1_M02

Down MH: MY00001_P1_M02

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:00:10	0	AMH								MY00001_P1_M01
00:00:40	0	MWL				5				
00:01:17	18.3	ISJ					True	12		
00:02:07	33.6	FC					True	8	9	
00:03:21	49.2	IR					True	9	3	
00:03:27	49.2	DAE				5	True	7	5	
00:03:27	64.2	DAE				5		7	9	
00:03:58	64.2	TBI		10	5			10		
00:05:21	80.7	B					True	4	5	

YOUNGSTOWNE — January 31 2024

Up MH: MY00001_P1_M01

Pipe: MY00001_P1_M01-MY00001_P1_M02

Down MH: MY00001_P1_M02

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:05:35	80.7	ID					True	5		
00:06:49	99.6	AMH								MY00001_P1_M02

YOUNGSTOWNE — January 31 2024

Up MH: MY00001_P1_M01

Pipe: MY00001_P1_M01-MY00001_P1_M02

Down MH: MY00001_P1_M02

Additional PACP Header Information

Media Label:		Up Rim to Invert:	16
Work Order:		Up Rim to Grade:	0
Sheet Number:		Up Grade to Invert:	16
Date Cleaned:	January 29 2024	Up Northing:	
Flow Control:		Up Easting:	
Consequence of Failure		Up Elevation:	
Pressure Value:		Down Rim to Invert:	17
Drainage Area:		Down Rim to Grade:	0
Location Code:	D	Down Grade to Invert:	17
Location Details:	1458 TURNBERRY DR	Down Northing:	
Coating Method:		Down Easting:	
Pipe Joint Length:		Down Elevation:	
Year Constructed:		Coordinate System:	
Year Renewed:		Vertical Datum:	
		GPS Accuracy:	
Reverse Setup:	0	Imperial?:	True