

Project:	2420009	Date/Time:	February 1 2024 - 12:53
Street and City:	TURNBERRY DR - YOUNGSTOWN	Weather:	Dry Weather/Wet Ground
Owner:	CITY OF YOUNGSTOWN	Inspection Status:	Complete Inspection
Customer:	CT CONSULTANTS	Segment:	MY00001_P1_M02-MY00001_P1_M03
Surveyor Name and Certificate:	SHAWN DUNNELL U-915-70001437	Direction:	Upstream
Reviewer Name and Certificate:		Up MH:	MY00001_P1_M02
P.O. #		Down MH:	MY00001_P1_M03

Pipe Details and Measurements

Pipe Use:	SW	Material:	CMP
Height:	26	Lining:	
Width:	36	Joint Length:	
Shape:	A	Purpose:	F
Pre-Cleaning:	No Pre-Cleaning	Additional Info:	

Pipe Ratings

Overall Quick Rating: 5232

Structural Quick Rating:	5232	O&M Quick Rating:	2312
Structural Pipe Rating Index:	4.0	O&M Pipe Rating Index:	1.6



Surveyed Length: 23

Total Length:

Inspection Technology Used: CCTV

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M02

Pipe: MY00001_P1_M02-MY00001_P1_M03

Down MH: MY00001_P1_M03

Observations & Defects


Surveyed Length: 23

Total Length: 23

Flow Direction:



Survey Direction:
Upstream







YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M02

Pipe: MY00001_P1_M02-MY00001_P1_M03

Down MH: MY00001_P1_M03





Photo	Distance	Description	Time
	0	AMH - Manhole Remark = MY00001_P1_M03	00:00:12
	0	MWL - Miscellaneous Water Level Percent: 25	00:00:25
	0	DSGV - Deposits Settled Gravel Continuous: S01 Percent: 10 Clock from 5 to 7 Grade = 2	00:00:28
	0	LL - Line Left Percent: 10 Grade = 1	00:00:41

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M02

Pipe: MY00001_P1_M02-MY00001_P1_M03

Down MH: MY00001_P1_M03





Photo	Distance	Description	Time
	4.5	HSV - Hole Soil Visible Clock At 8 Grade = 5	00:01:43
	12.9	MWL - Miscellaneous Water Level Percent: 5	00:03:08
	12.9	SCP - Surface Damage Corrosion Continuous: S02 Clock from 5 to 7 Grade = 3	00:03:14
	12.9	DSGV - Deposits Settled Gravel Continuous: F01 Percent: 10 Clock from 5 to 7 Grade = 2	00:03:23

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M02

Pipe: MY00001_P1_M02-MY00001_P1_M03

Down MH: MY00001_P1_M03


Photo	Distance	Description	Time
	18.6	HSV - Hole Soil Visible Continuous: S03 Joint: True Clock from 4 to 7 Grade = 5	00:06:01
	20.1	LL - Line Left Percent: 10 Grade = 1	00:04:04
	23	HSV - Hole Soil Visible Continuous: F03 Joint: True Clock from 4 to 7 Grade = 5	00:07:35
	23	SCP - Surface Damage Corrosion Continuous: F02 Clock from 5 to 7 Grade = 3	00:07:40

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M02

Pipe: MY00001_P1_M02-MY00001_P1_M03

Down MH: MY00001_P1_M03

Photo	Distance	Description	Time
	23	MSA - Miscellaneous Survey Abandoned Remark = HOLE IN THE PIPE	00:07:48

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M02

Pipe: MY00001_P1_M02-MY00001_P1_M03

Down MH: MY00001_P1_M03

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:00:12	0	AMH								STM_MH_3
00:00:25	0	MWL				25				
00:00:28	0	DSG V	S01			10		5	7	
00:00:41	0	LL				10				
00:01:43	4.5	HSV						8		
00:03:08	12.9	MWL				5				
00:03:08	12.9	SCP	S02					5	7	
00:03:23	12.9	DSG V	F01			10		5	7	
00:06:01	18.6	HSV	S03				True	4	7	

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M02

Pipe: MY00001_P1_M02-MY00001_P1_M03

Down MH: MY00001_P1_M03

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:04:04	20.1	LL				10				
00:07:35	23	HSV	F03				True	4	7	
00:07:40	23	SCP	F02					5	7	
00:07:48	23	MSA								HOLE IN THE PIPE

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M02

Pipe: MY00001_P1_M02-MY00001_P1_M03

Down MH: MY00001_P1_M03

Additional PACP Header Information

Media Label:		Up Rim to Invert:	16
Work Order:		Up Rim to Grade:	0
Sheet Number:		Up Grade to Invert:	16
Date Cleaned:	Unknown	Up Northing:	
Flow Control:		Up Easting:	
Consequence of Failure		Up Elevation:	
Pressure Value:		Down Rim to Invert:	17
Drainage Area:		Down Rim to Grade:	0
Location Code:	D	Down Grade to Invert:	17
Location Details:		Down Northing:	
Coating Method:		Down Easting:	
Pipe Joint Length:		Down Elevation:	
Year Constructed:		Coordinate System:	
Year Renewed:		Vertical Datum:	
		GPS Accuracy:	
Reverse Setup:	0	Imperial?:	True