

Project:	2420009	Date/Time:	February 1 2024 - 12:29
Street and City:	TURNBERRY DR - YOUNGSTOWN	Weather:	Dry Weather/Wet Ground
Owner:	CITY OF YOUNGSTOWN	Inspection Status:	Complete Inspection
Customer:	CT CONSULTANTS	Segment:	MY00001_P1_M03-MY00001_P1_M04
Surveyor Name and Certificate:	SHAWN DUNNELL U-915-70001437	Direction:	Upstream
Reviewer Name and Certificate:		Up MH:	MY00001_P1_M03
P.O. #		Down MH:	MY00001_P1_M04

Pipe Details and Measurements

Pipe Use:	SW	Material:	CMP
Height:	30	Lining:	
Width:	46	Joint Length:	
Shape:	A	Purpose:	F
Pre-Cleaning:	No Pre-Cleaning	Additional Info:	

Pipe Ratings

Overall Quick Rating: 524C

Structural Quick Rating:	524C	O&M Quick Rating:	3124
Structural Pipe Rating Index:	4.0	O&M Pipe Rating Index:	2.2



Surveyed Length: 186.3

Total Length:

Inspection Technology Used: CCTV

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M03

Pipe: MY00001_P1_M03-MY00001_P1_M04

Down MH: MY00001_P1_M04

Observations & Defects


Surveyed Length: 186.3

Total Length: 186.3

Flow Direction:



Survey Direction:
Upstream







YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M03

Pipe: MY00001_P1_M03-MY00001_P1_M04

Down MH: MY00001_P1_M04





Photo	Distance	Description	Time
	0	AMH - Manhole Remark = MY00001_P1_M04	00:00:14
	0	MWL - Miscellaneous Water Level Percent: 30	00:00:23
	3	HSV - Hole Soil Visible Clock from 5 to 7 Grade = 5	00:00:51
	3	OBR - Obstruction Rocks Percent: 15 Clock from 5 to 7 Grade = 3	00:01:12

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M03

Pipe: MY00001_P1_M03-MY00001_P1_M04

Down MH: MY00001_P1_M04





Photo	Distance	Description	Time
	30.6	OBB - Obstruction Brick or Masonry Percent: 5 Clock At 6 Grade = 2	00:03:45
	33.9	SRV - Surface Damage Reinforcement Visible Continuous: S01 Clock from 4 to 8 Grade = 4	00:04:03
	36.6	OBB - Obstruction Brick or Masonry Percent: 5 Clock At 6 Grade = 2	00:04:15
	42.6	H - Hole Clock from 5 to 6 Grade = 4	00:04:44

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M03

Pipe: MY00001_P1_M03-MY00001_P1_M04

Down MH: MY00001_P1_M04



Photo	Distance	Description	Time
	126	HSV - Hole Soil Visible Clock At 9 Grade = 5	00:09:41
	130.8	SRV - Surface Damage Reinforcement Visible Continuous: F01 Clock from 4 to 8 Grade = 4	00:10:07
	177.6	SSS - Surface Damage Surface Spalling Clock At 1 Grade = 2	00:11:13
	183.3	OBR - Obstruction Rocks Percent: 5 Clock At 6 Grade = 2	00:11:46

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M03

Pipe: MY00001_P1_M03-MY00001_P1_M04

Down MH: MY00001_P1_M04

Photo	Distance	Description	Time
	184.8	DSGV - Deposits Settled Gravel Percent: 10 Clock from 5 to 7 Grade = 2	00:12:24
	186.3	ACB - Access Point Catch Basin Remark = MY00001_P1_M03	00:12:47

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M03

Pipe: MY00001_P1_M03-MY00001_P1_M04

Down MH: MY00001_P1_M04

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:00:14	0	AMH								MY00001_P1_M04
00:00:23	0	MWL				30				
00:00:51	3	HSV						5	7	
00:01:12	3	OBR				15		5	7	
00:03:45	30.6	OBB				5		6		
00:04:03	33.9	SRV	S01					4	8	
00:04:03	36.6	OBB				5		6		
00:04:44	42.6	H						5	6	
00:09:41	126	HSV						9		

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M03

Pipe: MY00001_P1_M03-MY00001_P1_M04

Down MH: MY00001_P1_M04

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:10:07	130.8	SRV	F01					4	8	
00:11:13	177.6	SSS						1		
00:11:46	183.3	OBR				5		6		
00:12:24	184.8	DSG V				10		5	7	
00:12:47	186.3	ACB								MY00001_P1_M03

YOUNGSTOWN — February 1 2024

Up MH: MY00001_P1_M03

Pipe: MY00001_P1_M03-MY00001_P1_M04

Down MH: MY00001_P1_M04

Additional PACP Header Information

Media Label:		Up Rim to Invert:	16
Work Order:		Up Rim to Grade:	0
Sheet Number:		Up Grade to Invert:	16
Date Cleaned:	Unknown	Up Northing:	
Flow Control:		Up Easting:	
Consequence of Failure		Up Elevation:	
Pressure Value:		Down Rim to Invert:	17
Drainage Area:		Down Rim to Grade:	0
Location Code:	D	Down Grade to Invert:	17
Location Details:		Down Northing:	
Coating Method:		Down Easting:	
Pipe Joint Length:		Down Elevation:	
Year Constructed:		Coordinate System:	
Year Renewed:		Vertical Datum:	
		GPS Accuracy:	
Reverse Setup:	0	Imperial?:	True