

Project:	2420009	Date/Time:	January 31 2024 - 12:16
Street and City:	TURNBERRY DR - YOUNGSTOWN	Weather:	Dry Weather/Wet Ground
Owner:	CITY OF YOUNGSTOWN	Inspection Status:	Complete Inspection
Customer:	CT CONSULTANTS	Segment:	MY00001_P1_M04-MY00001_P1_M05
Surveyor Name and Certificate:	SHAWN DUNNELL U-915-70001437	Direction:	Upstream
Reviewer Name and Certificate:		Up MH:	MY00001_P1_M04
P.O. #		Down MH:	MY00001_P1_M05

Pipe Details and Measurements

Pipe Use:	SW	Material:	CMP
Height:	36	Lining:	
Width:	64	Joint Length:	
Shape:	E	Purpose:	F
Pre-Cleaning:	No Pre-Cleaning	Additional Info:	

Pipe Ratings

Overall Quick Rating: 3C21

Structural Quick Rating:	3C00	O&M Quick Rating:	2100
Structural Pipe Rating Index:	3.0	O&M Pipe Rating Index:	2.0



Surveyed Length: 214.5

Total Length:

Inspection Technology Used: CCTV

YOUNGSTOWN — January 31 2024

Up MY00001_P1_M04

Pipe: MY00001_P1_M04-MY00001_P1_M05

Down MH: MY00001_P1_M05

Observations & Defects


Surveyed Length: 214.5

Total Length: 214.5

Flow Direction:



Survey Direction:
Upstream







YOUNGSTOWN — January 31 2024

Up MH: MY00001_P1_M04

Pipe: MY00001_P1_M04-MY00001_P1_M05

Down MH: MY00001_P1_M05





Photo	Distance	Description	Time
	0	AMH - Manhole Remark = MY00001_P1_M05	00:00:27
	0	MWL - Miscellaneous Water Level Percent: 15	00:00:39
	9.6	SCP - Surface Damage Corrosion Continuous: S01 Clock from 4 to 8 Grade = 3	00:01:14
	126.6	SCP - Surface Damage Corrosion Continuous: F01 Clock from 4 to 8 Grade = 3	00:05:51

YOUNGSTOWN — January 31 2024

Up MH: MY00001_P1_M04

Pipe: MY00001_P1_M04-MY00001_P1_M05

Down MH: MY00001_P1_M05

Photo	Distance	Description	Time
	135	MWL - Miscellaneous Water Level Percent: 25	00:06:09
	150.6	MWL - Miscellaneous Water Level Percent: 5	00:06:45
	172.5	OBR - Obstruction Rocks Percent: 10 Clock At 6 Grade = 2	00:08:03
	214.5	ACB - Access Point Catch Basin Remark = MY00001_P1_M04	00:10:10

YOUNGSTOWN — January 31 2024

Up MH: MY00001_P1_M04

Pipe: MY00001_P1_M04-MY00001_P1_M05

Down MH: MY00001_P1_M05

Time	Dist.	Code	Cont.	Dim. 1	Dim. 2	%	Joint	Clock From	Clock To	Remarks
00:00:27	0	AMH								MY00001_P1_M05
00:00:39	0	MWL				15				
00:01:14	9.6	SCP	S01					4	8	
00:05:51	126.6	SCP	F01					4	8	
00:06:09	135	MWL				25				
00:06:45	150.6	MWL				5				
00:06:45	172.5	OBR				10		6		
00:10:10	214.5	ACB								MY00001_P1_M04

YOUNGSTOWN — January 31 2024

Up MH: MY00001_P1_M04

Pipe: MY00001_P1_M04-MY00001_P1_M05

Down MH: MY00001_P1_M05

Additional PACP Header Information

Media Label:		Up Rim to Invert:	16
Work Order:		Up Rim to Grade:	0
Sheet Number:		Up Grade to Invert:	16
Date Cleaned:	January 29 2024	Up Northing:	
Flow Control:		Up Easting:	
Consequence of Failure		Up Elevation:	
Pressure Value:		Down Rim to Invert:	17
Drainage Area:		Down Rim to Grade:	0
Location Code:	D	Down Grade to Invert:	17
Location Details:		Down Northing:	
Coating Method:		Down Easting:	
Pipe Joint Length:		Down Elevation:	
Year Constructed:		Coordinate System:	
Year Renewed:		Vertical Datum:	
		GPS Accuracy:	
Reverse Setup:	0	Imperial?:	True