

0000033718 - Mead Township Road Repairs (Slope Repairs) - Mead Township Trustees

Opinion of Probable Construction Cost: \$1,443,000.00

<i>BIDDER NAME</i>	<i>Bond/Check</i>	<i>Addendum Received 1</i>	<i>Site 2 McGee Road Slope Repair</i>	<i>Site 3 Lower Cash Ridge Road Slope Repair</i>	<i>Site 5 Turkey Point Road Slope Repair</i>	<i>Site 6 Lashely Road Slope Repair</i>	<i>Site 7 Ray Ramsey Road Slope Repair</i>	
<i>Alan Stone Company, Inc.</i>			311,892.	171,268.	148,295.	196,613.	226,436.	1,054,
<i>Dennison Bridge, Inc.</i>			401,413.50	236,818.	184,755.	257,139.50	323,131.	1,403,2
<i>Ohio-West Virginia Excavating Co.</i>			249,076.	147,182.	110,129.	168,121.50	189,174.	863,68

Z:\Project Files\MA-NZ\Meadtwp\33718 - Mead Township Road Slip Repairs\Working\Bid Documents\Ph 1 - Sites 2, 3, 5, 6, & 7\Bid Opening Report\Bid Opening Report.Doc

